Overton's JUMP SEAT ASSEMBLY INSTRUCTIONS

MODEL NO'S.

- WD1414
- WD1034
- WD1406
- WD1384
- WD1042
- Phillips head screwdriver is only tool required
- By shipping this product to you unassembled, freight costs are greatly reduced



- Set up side panels 3 and 6 parallel to each other with the square face to front.
- Slide front panel **D** into notch on both side panels simultaneously.
- Slide black spacer bar into U-shaped holes at bottom of side panels.



• Slide back rest **(** downward into notches at rear of base.




- Attach 4 screws into bottom side corners of base through pre-drilled holes, one in each corner.
- Attach 2 screws through base bottom into black spacer bar



 Snap seat cushion down onto base with black square to front.

Questions? Missing Parts? Call 1.800.334.6541

Above items are not manufactured for commercial use.



Overton's

WF 1135WG-O